



CORRENTE SIMPLES

REFERÊNCIA	PASSO	ISO	A	h	W	H	Kg/m
LA - 0	3/8"	06 - B1	5.5	1.5	15	10	0.130
LA - 1	1/2"	08 - B1	7.5	2.2	20	10	0.165
LA - 2	1/2"	08 - B1	7.5	2.2	20	15	0.26
LA - 3	5/8"	10 - B1	9.3	2.6	20	10	0.16
LA - 4	5/8"	10 - B1	9.3	2.6	20	15	0.26
LA - 5	3/4"	12 - B1	11.3	2.4	25	10	0.21
LA - 6	3/4"	12 - B1	11.3	2.4	25	15	0.325
LA - 7	1"	16 - B1	16.5	3.5	40	15	0.47
LA - 8	1"	16 - B1	16.5	3.5	40	20	0.66
LA - 9	1" ¼	20 - B1	19	4.2	45	15	0.53
LA - 10	1" ¼	20 - B1	19	4.3	45	20	0.72
LA - 11	1" ½	24 - B1	24.7	5.5	60	15	0.665
LA - 12	1" ¾	28 - B1	30.1	6.8	75	20	1.13
LA - 13	2"	32 - B1	30.1	7.7	80	20	1.15
LA - 14	2"	32 - B1	30.1	7.7	85	20	1.21