



| REFERÊNCIA | PASSO | ISO | W | V | H | K | h | A | CALHA | Kg/m |
|-------------|-------|---------|----|------|----|----|-----|------|--------|-------|
| LA - 54 | 3/8" | 06 - B1 | 20 | 15 | 15 | 17 | 1.5 | 5.4 | C 2010 | 0.620 |
| LA - 55 | 1/2" | 08 - B1 | 24 | 20 | 9 | 11 | 2.2 | 7.5 | C 2405 | 0.120 |
| LA - 55 - A | 1/2" | 08 - B1 | 20 | 17 | 15 | 17 | 2.2 | 7.5 | C 2010 | 0.130 |
| LA - 56 | 5/8" | 10 - B1 | 20 | 17 | 15 | 17 | 2.6 | 9.3 | C 2010 | 0.135 |
| LA - 57 | 3/4" | 12 - B1 | 20 | 20 | 15 | 17 | 2.4 | 11.3 | C 2812 | 0.175 |
| LA - 57 - A | 3/4" | 12 - B1 | 28 | 23.5 | 15 | 18 | 2.4 | 11.3 | C 2812 | 0.289 |
| LA - 58 | 1" | 16 - B1 | 28 | 23.5 | 15 | 18 | 3.5 | 16.5 | C 2812 | 0.297 |
| LA - 59 | 1" ¼ | 20 - B1 | 28 | 28 | 15 | 18 | 4.3 | 19.0 | C 2812 | 0.345 |
| LA - 60 | 1" ½ | 24 - B1 | 38 | 33 | 25 | 30 | 5.5 | 24.7 | C 3818 | 0.635 |
| LA - 61 | 1" ¾ | 28 - B1 | 38 | 38 | 25 | 30 | 6.8 | 30.1 | C 3818 | 0.731 |
| LA - 62 - A | 2" | 32 - B1 | 38 | 38 | 25 | 30 | 7.7 | 30.1 | C 3818 | 0.710 |
| LA - 62 - B | 2" | 32 - B1 | 60 | 60 | 25 | 35 | 7.7 | 30.1 | C 6020 | 1.240 |